
## **VENTILATION AUDIT REPORT**



SCHOOL:	Cascade Environmental Education Centre (5731)
AMU REGION:	North Coast
STATE ELECTORATE:	Oxley
LOCAL GOVERNMENT AREA:	Bellingen





## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
$\bigcirc$	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Staff Room - (17.81 SQM)	Office (4)	
B00A - R0003 - Clerical Office/Workroom - (17.44 SQM)	Office (4)	
B00A - R0004 - Movement - (9.52 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Dormitory - (8 SQM)	Office (2)	
B00B - R0003 - Dormitory - (46.57 SQM)	Office (11)	
B00C - R0004 - Dormitory - (9.29 SQM)	Office (2)	
B00C - R0006 - Dormitory - (43.83 SQM)	Office (10)	
B00F - R0004 - Staff Kitchen - (24.56 SQM)	Office (6)	
B00F - R0006 - Practical Activities - (17.67 SQM)	Student Space (8)	
OS 601 10114 - OS 601 10114 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	