


VENTILATION AUDIT REPORT











SCHOOL:	Central Mangrove Public School (4110)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Gosford
LOCAL GOVERNMENT AREA:	Central Coast

4110 - Central Mangrove Public School
Site Plan (10244)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0005 - Home Base - (57.47 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0007 - Outdoor Learning Area - (19.6 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Home Base - (53.47 SQM) - Teaching Space: 1	 Student Space (24)	
B00B - R0002 - Home Base - (53.47 SQM) - Teaching Space: 1	 Student Space (24)	
B00B - R0003 - Staff Room Annexe - (10.73 SQM)	 Office (2)	
B00F - R0001 - Canteen - (22.45 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Reading Area - (70.46 SQM)	 Student Space (32)	
B00G - R0005 - Movement - (19.2 SQM)	Not Applicable	Circulation or storage space.
B00G - R0006 - Clerical Office - (17.69 SQM)	 Office (4)	
B00G - R0007 - Principal - (15.75 SQM)	 Office (3)	
B00G - R0009 - Staff Kitchen - (5.67 SQM)	 Office (1)	
B00G - R0010 - Staff Room - (20.89 SQM)	 Office (5)	
B00G - R0013 - Sick Bay - (7.39 SQM)	 Student Space (3)	