


# VENTILATION AUDIT REPORT












<b>SCHOOL:</b>	<b>Central Tilba Public School (3214)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Bega</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Eurobodalla</b>

3214 - Central Tilba Public School  
Site Plan (11991)



## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (5.6 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Movement - (28.2 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Withdrawal Space - 1hb - (11.56 SQM)	 Student Space (5)	
B00A - R0004 - Practical Activities - 1hb - (7.84 SQM)	 Student Space (3)	
B00A - R0005 - Withdrawal Space - 1hb - (36.96 SQM)	 Student Space (17)	
B00A - R0006 - Home Base - (44.8 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R9002 - Darkroom Space - (9.66 SQM)	 Office (2)	
B00E - R0002 - Reading Area - (56.02 SQM)	 Student Space (25)	
B00E - R0005 - Clerical Office/Workroom - (10.62 SQM)	 Office (2)	
B00E - R0006 - Principal - (10.62 SQM)	 Office (2)	
B00E - R0007 - Clerical Office - (10.69 SQM)	 Office (2)	
B00H - R0003 - Home Base - (61.39 SQM) - Teaching Space: 1	 Student Space (28)	
OS 531 14491 - OS 531 14491 - Library - (76 SQM)	 Student Space (35)	