

VENTILATION AUDIT REPORT

SCHOOL:	Chandler Public School (1547)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Armidale

1547 - Chandler Public School
Site Plan (11430)










1:496

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office/Workroom - (16.77 SQM)	 Office (4)	
B00A - R0002 - Reading Area - (58.79 SQM)	 Student Space (27)	
B00A - R0005 - Staff Kitchen - (8.29 SQM)	 Office (2)	
B00A - R0006 - Principal - (5.3 SQM)	 Office (1)	
B00B - R0001 - Canteen - (20.3 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Movement - (23.86 SQM)	Not Applicable	Circulation or storage space.
B00D - R0005 - Home Base - (73.01 SQM) - Teaching Space: 1	 Student Space (33)	
B00D - R0006 - Practical Activities - 1hb - (13.97 SQM)	 Student Space (6)	
B00E - R0001 - Home Base - (59.98 SQM) - Teaching Space: 1	 Student Space (27)	