

VENTILATION AUDIT REPORT




SCHOOL:	Clare Public School (4565)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Balranald

4565 - Clare Public School
Site Plan (10606)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0001 - Clerical Office - (16.01 SQM)	 Office (4)	
B00D - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (27)	
OS 601 12367 - OS 601 12367 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	