VENTILATION AUDIT REPORT



SCHOOL:	Clergate Public School (2668)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Cabonne

2668 - Clergate Public School Site Plan (10236)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (10.02 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Clerical Office - (10.61 SQM)	Office (2)	
B00A - R0004 - Principal - (13.68 SQM)	Office (3)	
B00A - R0005 - Staff Room - (25.88 SQM)	Office (6)	
B00A - R0008 - Entry Vestibule - (8.04 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Withdrawal Space - 1hb - (13.51 SQM)	Student Space (6)	
B00B - R0002 - Home Base - (53.25 SQM) - Teaching Space: 1	Student Space (24)	
B00C - R0001 - Movement - (14.63 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Practical Activity Area - (33.92 SQM)	Student Space (15)	
B00G - R0001 - Communal Space - (59.69 SQM)	Student Space (27)	
B00J - R0001 - Home Base - (60.67 SQM) - Teaching Space: 1	Student Space (28)	
OS 531 16224 - OS 531 16224 - Library - (76 SQM)	Student Space (35)	
OS 601 13783 - OS 601 13783 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 602 13644 - OS 602 13644 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	
OS 602 14878 - OS 602 14878 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	