

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Collector Public School (1590)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Goulburn</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Upper Lachlan</b>

1590 - Collector Public School  
Site Plan (10937)













1:517

Printed: 05-Sep-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Clerical Office - (8.46 SQM)	 Office (2)	
B00A - R0004 - Home Base - (44.22 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0005 - Practical Activities - 1hb - (16.01 SQM)	 Student Space (7)	
B00B - R0002 - Reading Area - (21.9 SQM)	 Student Space (10)	
B00F - R0002 - Communal Space - (66.35 SQM)	 Student Space (30)	
B00G - R0002 - Reading Area - (31.93 SQM)	 Student Space (14)	
B00G - R0005 - Reading Area - (19.79 SQM)	 Student Space (9)	
B00G - R0006 - Canteen - (12.05 SQM)	Not Applicable	Circulation or storage space.
B00G - R0007 - Movement - (10.09 SQM)	Not Applicable	Circulation or storage space.
B00I - R0002 - Clerical Office/Workroom - (16.2 SQM)	 Office (4)	
B00I - R0003 - Clerical Office - (16.2 SQM)	 Office (4)	
B00I - R0005 - Movement - (6.88 SQM)	Not Applicable	Circulation or storage space.
OS 601 12157 - OS 601 12157 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	