

VENTILATION AUDIT REPORT



SCHOOL:	Collins Creek Public School (1593)	
AMU REGION:	North Coast	
STATE ELECTORATE:	Lismore	
LOCAL GOVERNMENT AREA:	Kyogle	





Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Withdrawal Space - 1hb - (8.61 SQM)	Student Space (3)	
B00A - R0003 - Practical Activities - 1hb - (9.41 SQM)	Student Space (4)	
B00A - R0004 - Home Base - (41.76 SQM) - Teaching Space: 1	Student Space (19)	
B00A - R0005 - Staff Room Annexe - (5.77 SQM)	Office (1)	
B00A - R0006 - Staff Room - (6.85 SQM)	Office (1)	
B00B - R0001 - Movement - (14.35 SQM)	Not Applicable	Circulation or storage space.
B00B - R0006 - Reading Area - (42.23 SQM)	Student Space (19)	
B00F - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	Student Space (27)	