

VENTILATION AUDIT REPORT







SCHOOL:	Conargo Public School (1606)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Edward River

1606 - Conargo Public School
Site Plan (10939)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (8.85 SQM)	 Office (2)	
B00A - R0002 - Movement - (13.26 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Home Base - (53.36 SQM) - Teaching Space: 1	 Student Space (24)	
B00D - R0002 - Reading Area - (38.26 SQM)	 Student Space (17)	
B00D - R0006 - Staff Kitchen - (14.31 SQM)	 Office (3)	
B00E - R0003 - Home Base - (75.92 SQM) - Teaching Space: 1	 Student Space (35)	
B00F - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	