

VENTILATION AUDIT REPORT



SCHOOL:	Corndale Public School (1656)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Lismore





Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Home Base - (43.62 SQM) - Teaching Space: 1	Student Space (20)	
B00A - R0004 - Reading Area - (43.17 SQM)	Student Space (20)	
B00A - R0005 - Staff Room - (11.03 SQM)	Office (2)	
B00A - R0009 - Entry Vestibule - (16.07 SQM)	Not Applicable	Circulation or storage space.
B00A - R0010 - Movement - (14.07 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Principal - (13.26 SQM)	Office (3)	
B00B - R0001 - Canteen - (13.81 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Interview - (14.45 SQM)	Office (3)	
B00D - R0002 - Interview - (13.3 SQM)	Office (3)	
B00D - R0007 - Movement - (8.74 SQM)	Not Applicable	Circulation or storage space.
B00D - R0012 - Interview - (14.41 SQM)	Office (3)	
B00D - R0013 - Withdrawal Space - 1hb - (23.66 SQM)	Student Space (10)	
B00D - R0017 - Staff Kitchen - (11.2 SQM)	Office (2)	