


VENTILATION AUDIT REPORT







SCHOOL:	Cowper Public School (1670)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Clarence Valley

1670 - Cowper Public School
Site Plan (14702)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Practical Activities - 1hb - (18.22 SQM)	 Student Space (8)	
B00A - R0003 - Withdrawal Space - 1hb - (23.04 SQM)	 Student Space (10)	
B00A - R0005 - Reading Area - (44.33 SQM)	 Student Space (20)	
B00A - R0006 - Home Base - (44.03 SQM)	 Student Space (20)	
B00C - R0001 - Movement - (10.48 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Canteen - (10.73 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Home Base - (60 SQM) - Teaching Space: 1	 Student Space (27)	
B00G - R0005 - Home Base - (60 SQM) - Teaching Space: 1	 Student Space (27)	