


VENTILATION AUDIT REPORT

SCHOOL:	Croppa Creek Public School (3717)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Gwydir

3717 - Croppa Creek Public School
Site Plan (10946)













1:1,108

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Reading Area - (12.32 SQM)	 Student Space (5)	
B00A - R0003 - Special Programs Room - (20.49 SQM)	 Student Space (9)	
B00B - R0002 - Home Base - (48.46 SQM) - Teaching Space: 1	 Student Space (22)	
B00B - R0004 - Movement - (10.89 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Movement - (18.56 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Principal - (7.75 SQM)	 Office (1)	
B00C - R0005 - Home Base - (50.68 SQM) - Teaching Space: 1	 Student Space (23)	
B00D - R0007 - Movement - (7.38 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Staff Room - (14.92 SQM)	 Office (3)	
B00E - R0002 - Staff Room Annexe - (5.4 SQM)	 Office (1)	
B00E - R0003 - Movement - (12.82 SQM)	Not Applicable	Circulation or storage space.
B00E - R0004 - Clerical Office/Workroom - (35.16 SQM)	 Office (8)	
B00F - R0001 - Home Base - (109.19 SQM) - Teaching Space: 1	 Student Space (50)	
B00H - R0002 - Reading Area - (60.79 SQM)	 Student Space (28)	