

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Crossmaglen Public School (1685)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Coffs Harbour</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Coffs Harbour</b>

1685 - Crossmaglen Public School  
Site Plan (10299)



## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0010 - Staff Kitchen - (7.21 SQM)	Office (1)	
B00A - R0011 - Clerical Office/Workroom - (42 SQM)	Office (10)	
B00A - R0012 - Principal - (7.64 SQM)	Office (1)	
B00C - R0001 - Canteen - (11.2 SQM)	Not Applicable	Circulation or storage space.
OS 531 15359 - OS 531 15359 - Library - (76 SQM)	Student Space (35)	
OS 601 10636 - OS 601 10636 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 602 19791 - OS 602 19791 - Learning Unit - Standard With P.A.A. - (76 SQM)	Student Space (35)	