


VENTILATION AUDIT REPORT

SCHOOL:	Cudal Public School (1695)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Cabonne

1695 - Cudal Public School
Site Plan (12695)














1:638

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (63.7 SQM) - Teaching Space: 1	 Student Space (29)	
B00A - R0004 - Home Base - (93.12 SQM) - Teaching Space: 1	 Student Space (43)	
B00A - R0006 - Clerical Office - (16.82 SQM)	 Office (4)	
B00A - R0007 - Entry Vestibule - (10.65 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Principal - (16.6 SQM)	 Office (4)	
B00B - R0001 - Movement - (43.98 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Home Base - (53.39 SQM) - Teaching Space: 1	 Student Space (24)	
B00B - R0003 - Home Base - (67.09 SQM) - Teaching Space: 1	 Student Space (31)	
B00B - R0007 - Reading Area - (57.01 SQM)	 Student Space (26)	
B00B - R0011 - Home Base - (57.23 SQM) - Teaching Space: 1	 Student Space (26)	
B00B - R0013 - Practical Activities - 1hb - (9.47 SQM)	 Student Space (4)	
B00B - R0014 - Staff Room - (28.98 SQM)	 Office (7)	
B00F - R0002 - Reading Area - (92.78 SQM)	 Student Space (43)	