


VENTILATION AUDIT REPORT

SCHOOL:	Cumnock Public School (1707)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Cabonne

1707 - Cumnock Public School
Site Plan (10744)













1:944

Printed: 08-Aug-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room - (31.61 SQM)	 Office (7)	
B00D - R0003 - Reading Area - (40.05 SQM)	 Student Space (18)	
B00E - R0002 - Clerical Office - (11.87 SQM)	 Office (2)	
B00E - R0003 - Principal - (9.64 SQM)	 Office (2)	
B00E - R0004 - Home Base - (66.33 SQM) - Teaching Space: 1	 Student Space (30)	
B00F - R0001 - Home Base - (48.17 SQM) - Teaching Space: 1	 Student Space (22)	
B00F - R0002 - Home Base - (53.23 SQM) - Teaching Space: 1	 Student Space (24)	
B00F - R0003 - Staff Kitchen - (9.91 SQM)	 Office (2)	
B00F - R0004 - Movement - (18.71 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Reading Area - (91.21 SQM)	 Student Space (42)	
OS 531 11880 - OS 531 11880 - Library - (76 SQM)	 Student Space (35)	