
VENTILATION AUDIT REPORT



SCHOOL:	Currabubula Public School (1714)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Liverpool Plains

1714 - Currabubula Public School Site Plan (10616)



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00C - R0001 - Practical Activities - 1hb - (17.38 SQM)	Student Space (8)	
B00C - R0002 - Home Base - (52.13 SQM) - Teaching Space: 1	Student Space (24)	
B00C - R0003 - Movement - (35.79 SQM)	Not Applicable	Circulation or storage space.
B00C - R0004 - Withdrawal Space - 1hb - (12.02 SQM)	Student Space (5)	
B00C - R0005 - Home Base - (52.34 SQM) - Teaching Space: 1	Student Space (24)	
B00C - R0007 - Practical Activities - 1hb - (16.58 SQM)	Student Space (7)	
B00C - R0008 - Movement - (9.66 SQM)	Not Applicable	Circulation or storage space.
B00C - R0009 - Sick Bay - (5.87 SQM)	Student Space (2)	
B00C - R0012 - Principal - (12.79 SQM)	Office (3)	
B00C - R0013 - Clerical Office - (13.23 SQM)	Office (3)	
B00C - R0015 - Movement - (6.42 SQM)	Not Applicable	Circulation or storage space.
B00C - R0016 - Staff Room - (23.83 SQM)	Office (5)	
B00C - R0018 - Reading Area - (29.72 SQM)	Student Space (13)	
B00E - R0001 - Reading Area - (59.96 SQM)	Student Space (27)	