

# VENTILATION AUDIT REPORT

|                               |                                     |
|-------------------------------|-------------------------------------|
| <b>SCHOOL:</b>                | <b>Dalgety Public School (1722)</b> |
| <b>AMU REGION:</b>            | <b>Southern NSW</b>                 |
| <b>STATE ELECTORATE:</b>      | <b>Monaro</b>                       |
| <b>LOCAL GOVERNMENT AREA:</b> | <b>Snowy Monaro</b>                 |

1722 - Dalgety Public School  
Site Plan (10134)








1:472

Printed: 07-Apr-2020

## Ventilation Audit Key

| Category  | Description  |
|---|--|
|  | Category A<br>Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation.<br>NB. Circulation and storage areas should not be used for groups or gatherings.   |
|  | Category B<br>This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> .<br>The report details the number of people who can be accommodated safely in each of the identified spaces. |

| Entity Location  | Audit Condition Classification (Capacity)  | Comment |
|--|--|---------|
| B00A - R0002 - Clerical Office - (24.44 SQM)               |  Office (6)         |         |
| B00A - R0003 - Principal - (11.24 SQM)                     |  Office (2)         |         |
| B00A - R0005 - Home Base - (53.43 SQM) - Teaching Space: 1 |  Student Space (24) |         |
| B00B - R0002 - Staff Room - (14.78 SQM)                    |  Office (3)         |         |
| B00B - R0003 - Reading Area - (53.47 SQM)                  |  Student Space (24) |         |