
VENTILATION AUDIT REPORT



SCHOOL:	Dalton Public School (1723)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Goulburn
LOCAL GOVERNMENT AREA:	Upper Lachlan



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office/Workroom - (21.66 SQM)	Office (5)	
B00A - R0002 - Reading Area - (40.32 SQM)	Student Space (18)	
B00A - R0006 - Principal - (14.2 SQM)	Office (3)	
B00A - R0008 - Interview - (14.59 SQM)	Office (3)	
B00A - R0009 - Movement - (6.76 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Staff Room - (17.77 SQM)	Office (4)	
B00A - R0012 - Staff Kitchen - (13.86 SQM)	Office (3)	
B00A - R0013 - Clerical Office - (24.13 SQM)	Office (6)	
B00A - R0014 - Sick Bay - (11.52 SQM)	Student Space (5)	
B00A - R0017 - Movement - (6.21 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Home Base - (53.07 SQM) - Teaching Space: 1	Student Space (24)	
B00B - R0003 - Withdrawal Space - 1hb - (10.42 SQM)	Student Space (4)	
B00C - R0005 - Movement - (30.36 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Special Programs Room - (10.38 SQM)	Student Space (4)	
B00D - R0002 - Movement - (13.8 SQM)	Not Applicable	Circulation or storage space.
B00D - R0003 - Staff Room - (13.68 SQM)	Office (3)	
B00D - R0004 - Movement - (36.92 SQM)	Not Applicable	Circulation or storage space.
B00G - R0002 - Home Base - (61.17 SQM) - Teaching Space: 1	Student Space (28)	