


VENTILATION AUDIT REPORT

SCHOOL:	Dorrourby Environmental Education Centre (5683)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Lismore

5683 - Dorrourby Environmental Education Centre
Site Plan (11699)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (24.66 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Clerical Office/Workroom - (15.32 SQM)	Office (3)	
B00A - R0004 - Reading Area - (35.84 SQM)	Student Space (16)	
B00A - R0006 - Clerical Office/Workroom - (15.72 SQM)	Office (3)	
B00A - R0007 - Clerical Office/Workroom - (18.03 SQM)	Office (4)	
B00A - R0018 - Principal - (8.12 SQM)	Office (2)	
B00C - R0002 - Dormitory - (7.37 SQM)	Office (1)	
B00C - R0003 - Dormitory - (44 SQM)	Office (11)	
B00C - R0005 - Dormitory - (7.27 SQM)	Office (1)	
B00C - R0006 - Dormitory - (44 SQM)	Office (11)	
B00G - R0001 - General Assistants - (13.73 SQM)	Office (3)	
OS 601 10604 - OS 601 10604 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	