

VENTILATION AUDIT REPORT

SCHOOL:	Doubtful Creek Public School (1769)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Kyogle

1769 - Doubtful Creek Public School
Site Plan (10957)











1:520

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Practical Activities - 1hb - (7.86 SQM)	 Student Space (3)	
B00A - R0003 - Withdrawal Space - 1hb - (13.44 SQM)	 Student Space (6)	
B00A - R0004 - Home Base - (34.72 SQM)	 Student Space (16)	
B00A - R0006 - Staff Room Annexe - (7.32 SQM)	 Office (1)	
B00D - R0005 - Clerical Office - (9.98 SQM)	 Office (2)	
B00D - R0008 - Staff Kitchen - (6.79 SQM)	 Office (1)	
B00D - R0009 - Principal - (8.23 SQM)	 Office (2)	
B00F - R0002 - Special Programs Room - (34 SQM)	 Student Space (15)	