

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Dundurrabin Public School (1788)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Clarence</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Clarence Valley</b>

1788 - Dundurrabin Public School  
Site Plan (11719)












1:744

Printed: 20-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Interview - (10.42 SQM)	 Office (2)	
B00A - R0005 - Home Base - (59.25 SQM) - Teaching Space: 1	 Student Space (27)	
B00A - R0006 - Practical Activities - 1hb - (6.3 SQM)	 Student Space (2)	
B00A - R0007 - Withdrawal Space - 1hb - (14.76 SQM)	 Student Space (6)	
B00A - R0008 - Sick Bay - (7.14 SQM)	 Student Space (3)	
B00B - R0002 - Canteen - (11 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Practical Activities - (40.7 SQM)	 Student Space (18)	
B00F - R0001 - Communal Space - (91.17 SQM)	 Student Space (42)	
B00G - R0001 - Reading Area - (61.12 SQM)	 Student Space (28)	
OS 505 18191 - OS 505 18191 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	