

VENTILATION AUDIT REPORT

SCHOOL:	Dungowan Public School (1793)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth

1793 - Dungowan Public School
Site Plan (14561)



1:938

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Movement - (40.19 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Practical Activities - 1hb - (8.18 SQM)	● Student Space (3)	
B00A - R0005 - Home Base - (62.99 SQM) - Teaching Space: 1	● Student Space (29)	
B00A - R0006 - Home Base - (66.41 SQM) - Teaching Space: 1	● Student Space (30)	
B00A - R0007 - Practical Activities - 1hb - (7.28 SQM)	● Student Space (3)	
B00A - R0008 - Clerical Office - (14.19 SQM)	● Office (3)	
B00A - R0010 - Staff Room - (9.49 SQM)	● Office (2)	
B00A - R0014 - Movement - (8.83 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Communal Space - (59.86 SQM)	● Student Space (27)	
OS 503 15293 - OS 503 15293 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	● Office (38)	