


VENTILATION AUDIT REPORT

SCHOOL:	Duranbah Public School (1801)
AMU REGION:	North Coast
STATE ELECTORATE:	Tweed
LOCAL GOVERNMENT AREA:	Tweed

1801 - Duranbah Public School
Site Plan (12485)










1:1,349

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0007 - Clerical Office - (16.07 SQM)	 Office (4)	
B00A - R0008 - Movement - (55.63 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Home Base - (73.6 SQM) - Teaching Space: 1	 Student Space (34)	
B00A - R0012 - Movement - (21.2 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - Home Base - (54.46 SQM) - Teaching Space: 1	 Student Space (25)	
B00A - R0015 - Duplicating Workroom - (8.52 SQM)	 Office (2)	
B00B - R0007 - Movement - (28.48 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Reading Area - (60.04 SQM)	 Student Space (27)	
OS 505 16847 - OS 505 16847 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	
OS 601 10599 - OS 601 10599 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	