

VENTILATION AUDIT REPORT



SCHOOL:	Duri Public School (1802)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth





Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Duplicating Workroom - (7.07 SQM)	Office (1)	
B00A - R0002 - Principal - (11.53 SQM)	Office (2)	
B00A - R0003 - Clerical Office - (16.38 SQM)	Office (4)	
B00A - R0006 - Staff Room - (15.56 SQM)	Office (3)	
B00B - R0001 - Movement - (21.07 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Reading Area - (58.97 SQM)	Student Space (27)	
B00B - R0006 - Movement - (11.85 SQM)	Not Applicable	Circulation or storage space.
B00B - R0007 - Movement - (5.08 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Movement - (34.66 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Practical Activities - 1hb - (19.03 SQM)	Student Space (8)	
B00C - R0003 - Home Base - (58.79 SQM) - Teaching Space: 1	Student Space (27)	
B00C - R0005 - Withdrawal Space - 1hb - (13.88 SQM)	Student Space (6)	
B00C - R0006 - Withdrawal Space - 2hb - (11.62 SQM)	Student Space (5)	
B00C - R0007 - Withdrawal Space - 1hb - (13.88 SQM)	Student Space (6)	
B00C - R0009 - Home Base - (58.79 SQM) - Teaching Space: 1	Student Space (27)	
B00C - R0010 - Practical Activities - 1hb - (19.03 SQM)	Student Space (8)	
B00D - R0001 - Reading Area - (59.96 SQM)	Student Space (27)	