


VENTILATION AUDIT REPORT

SCHOOL:	Ebor Public School (1814)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Armidale

1814 - Ebor Public School
Site Plan (12494)







1:696

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Reading Area - (23.29 SQM)	 Student Space (10)	
B00A - R0002 - Home Base - (53.69 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0004 - Principal - (11.22 SQM)	 Office (2)	
B00A - R0006 - Home Base - (68.92 SQM) - Teaching Space: 1	 Student Space (31)	