

VENTILATION AUDIT REPORT

SCHOOL:	Ellerston Public School (1830)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Upper Hunter

1830 - Ellerston Public School
Site Plan (10962)












1:563

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Home Base - (45.57 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0004 - Practical Activities - 1hb - (25.62 SQM)	 Student Space (11)	
B00A - R0005 - Staff Room - (8.61 SQM)	 Office (2)	
B00E - R0003 - Clerical Office - (17.61 SQM)	 Office (4)	
B00E - R0004 - Staff Kitchen - (17.33 SQM)	 Office (4)	
B00E - R0005 - Movement - (5.42 SQM)	Not Applicable	Circulation or storage space.
B00E - R0011 - Reading Area - (14.41 SQM)	 Student Space (6)	
B00E - R0012 - Principal - (11.2 SQM)	 Office (2)	
B00F - R0002 - Reading Area - (60.62 SQM)	 Student Space (28)	
OS 750 11794 - OS 750 11794 - Learning Unit - ESL - (38 SQM)	 Student Space (17)	