
## **VENTILATION AUDIT REPORT**



SCHOOL:	Empire Vale Public School (1840)
AMU REGION:	North Coast
STATE ELECTORATE:	Ballina
LOCAL GOVERNMENT AREA:	Ballina





## **Ventilation Audit Key**

Category	Description
	Category A  Operate this space in line with <a href="COVID safe school operations">COVID safe school operations</a> . It has the required level of natural ventilation.  NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with COVID safe school operations and the guided use of spaces.  The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Clerical Office/Workroom - (11.13 SQM)	Office (2)	
B00A - R0004 - Staff Room Annexe - (10.73 SQM)	Office (2)	
B00A - R0006 - Home Base - (67.21 SQM) - Teaching Space: 1	Student Space (31)	
B00A - R0007 - Staff Room - (15.24 SQM)	Office (3)	
B00B - R0001 - Practical Activities - 1hb - (22.75 SQM)	Student Space (10)	
B00B - R0004 - Reading Area - (44.44 SQM)	Student Space (20)	
B00C - R0001 - Movement - (9.96 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Canteen - (10.41 SQM)	Not Applicable	Circulation or storage space.
B00F - R0002 - Practical Activities - (19.41 SQM)	Student Space (9)	
B00F - R0004 - Home Base - (58.91 SQM) - Teaching Space: 1	Student Space (27)	
B00F - R0005 - Withdrawal Space - 2hb - (10.7 SQM)	Student Space (4)	
B00F - R0006 - Home Base - (58.82 SQM) - Teaching Space: 1	Student Space (27)	
B00F - R0008 - Practical Activities - (19.41 SQM)	Student Space (9)	