


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Enngonia Public School (3626)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Barwon</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Bourke</b>

3626 - Enngonia Public School  
Site Plan (12738)



1:512

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Canteen - (19.29 SQM)	Not Applicable	Circulation or storage space.
B00A - R0014 - Home Base - Pre - (97 SQM) - Teaching Space: 1	● Student Space (45)	
B00A - R0016 - Movement - (22.77 SQM)	Not Applicable	Circulation or storage space.
B00A - R0018 - Entry Vestibule - (19.3 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Clerical Office - (18.28 SQM)	● Office (4)	
B00B - R0003 - Entry Vestibule - (17.81 SQM)	Not Applicable	Circulation or storage space.
B00B - R0004 - Sick Bay - (8.88 SQM)	● Student Space (4)	
B00B - R0005 - Principal - (11.96 SQM)	● Office (2)	
B00B - R0007 - Staff Room - (18.27 SQM)	● Office (4)	
B00C - R0009 - Reading Area - (29.9 SQM)	● Student Space (13)	
B00C - R0011 - Home Base - (61 SQM) - Teaching Space: 1	● Student Space (28)	
B00C - R0012 - Practical Activities - 2hb - (25.13 SQM)	● Student Space (11)	
B00C - R0013 - Home Base - (60.97 SQM) - Teaching Space: 1	● Student Space (28)	