
VENTILATION AUDIT REPORT



SCHOOL:	Eugowra Public School (1870)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Cabonne



1870 - Eugowra Public School Site Plan (12509)

1:883

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
O	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (69.47 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Clerical Office - (9.77 SQM)	Office (2)	
B00A - R0003 - Principal - (11.89 SQM)	Office (2)	
B00A - R0004 - Reading Area - (98.85 SQM)	Student Space (45)	
B00A - R0006 - Home Base - (52.64 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R0007 - Home Base - (60.24 SQM) - Teaching Space: 1	Student Space (27)	
B00A - R0010 - Duplicating Workroom - (5.77 SQM)	Office (1)	
B00B - R0001 - Home Base - (62.57 SQM) - Teaching Space: 1	Student Space (29)	
B00B - R0003 - Home Base - (47.54 SQM) - Teaching Space: 1	Student Space (22)	
B00B - R0004 - Home Base - (47.6 SQM) - Teaching Space: 1	Student Space (22)	
B00B - R0005 - Home Base - (47.67 SQM) - Teaching Space: 1	Student Space (22)	
B00B - R0006 - Staff Room - (14.85 SQM)	Office (3)	
B00B - R0007 - Movement - (68.57 SQM)	Not Applicable	Circulation or storage space.
B00I - R0001 - Reading Area - (60.45 SQM)	Student Space (28)	
B00I - R0003 - Movement - (6.23 SQM)	Not Applicable	Circulation or storage space.