

VENTILATION AUDIT REPORT

| | |
|-------------------------------|--|
| SCHOOL: | Eurongilly Public School (1883) |
| AMU REGION: | Southern NSW |
| STATE ELECTORATE: | Cootamundra |
| LOCAL GOVERNMENT AREA: | Junee |

1883 - Eurongilly Public School
Site Plan (13036)







1:531

Printed: 02-Jul-2020

Ventilation Audit Key

| Category | Description |
|---|--|
|  | Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings. |
|  | Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces. |

| Entity Location | Audit Condition Classification (Capacity) | Comment |
|---|--|-------------------------------|
| B00A - R0004 - Principal - (15.44 SQM) |  Office (3) | |
| B00A - R0005 - Home Base - (57.6 SQM) - Teaching Space: 1 |  Student Space (26) | |
| B00A - R0007 - Movement - (6.16 SQM) | Not Applicable | Circulation or storage space. |
| B00A - R0008 - Movement - (29.66 SQM) | Not Applicable | Circulation or storage space. |
| B00A - R0009 - Withdrawal Space - 1hb - (33.43 SQM) |  Student Space (15) | |
| B00B - R0001 - Movement - (17.4 SQM) | Not Applicable | Circulation or storage space. |
| B00B - R0002 - Reading Area - (52.12 SQM) |  Student Space (24) | |