
VENTILATION AUDIT REPORT



SCHOOL:	Euston Public School (1885)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Balranald





Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Staff Room Annexe - (13.6 SQM)	Office (3)	
B00A - R0004 - Staff Room Annexe - (14.24 SQM)	Office (3)	
B00A - R0005 - Home Base - (56.4 SQM) - Teaching Space: 1	Student Space (26)	
B00A - R0009 - Home Base - (84.07 SQM) - Teaching Space: 1	Student Space (39)	
B00B - R0002 - Reading Area - (76.32 SQM)	Student Space (35)	
B00B - R0003 - Staff Room Annexe - (8.82 SQM)	Office (2)	
B00E - R0002 - Movement - (12.6 SQM)	Not Applicable	Circulation or storage space.
B00F - R0001 - Movement - (16.76 SQM)	Not Applicable	Circulation or storage space.
B00F - R0003 - Home Base - (46.96 SQM) - Teaching Space: 1	Student Space (21)	
B00H - R0002 - Practical Activities - 1hb - (21.61 SQM)	Student Space (10)	
B00H - R0004 - Home Base - (62.72 SQM) - Teaching Space: 1	Student Space (29)	
B00H - R0005 - Withdrawal Space - 2hb - (10.83 SQM)	Student Space (5)	
B00H - R0006 - Home Base - (62.73 SQM) - Teaching Space: 1	Student Space (29)	
B00H - R0008 - Practical Activities - 1hb - (21.61 SQM)	Student Space (10)	
OS 508 13973 - OS 508 13973 - Administration - (114 SQM)	Office (28)	