

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Fern Bay Public School (3996)</b>
<b>AMU REGION:</b>	<b>Hunter/Central Coast</b>
<b>STATE ELECTORATE:</b>	<b>Newcastle</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Port Stephens</b>

3996 - Fern Bay Public School  
Site Plan (12529)












1:568

Printed: 07-Jul-2021

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room Annexe - (5.43 SQM)	 Office (1)	
B00A - R0002 - Withdrawal Space - 1hb - (8.49 SQM)	 Student Space (3)	
B00A - R0003 - Home Base - (80.52 SQM) - Teaching Space: 1	 Student Space (37)	
B00E - R0001 - Movement - (21.69 SQM)	Not Applicable	Circulation or storage space.
B00F - R0002 - Practical Activities - (60.98 SQM)	 Student Space (28)	
OS 503 16263 - OS 503 16263 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	
OS 601 16791 - OS 601 16791 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	
OS 602 10221 - OS 602 10221 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	
OS 602 12721 - OS 602 12721 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	
OS 602 19793 - OS 602 19793 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	