

VENTILATION AUDIT REPORT



SCHOOL:	Fernleigh Public School (2214)
AMU REGION:	North Coast
STATE ELECTORATE:	Ballina
LOCAL GOVERNMENT AREA:	Ballina





Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Withdrawal Space - 1hb - (12.59 SQM)	Student Space (5)	
B00A - R0002 - Withdrawal Space - 1hb - (10.44 SQM)	Student Space (4)	
B00A - R0007 - Movement - (9.01 SQM)	Not Applicable	Circulation or storage space.
B00A - R0009 - Staff Kitchen - (12.44 SQM)	Office (3)	
B00A - R0012 - Movement - (8.67 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - Movement - (9.92 SQM)	Not Applicable	Circulation or storage space.
B00A - R0014 - Entry Vestibule - (15.09 SQM)	Not Applicable	Circulation or storage space.
B00A - R0015 - Principal - (13.09 SQM)	Office (3)	
B00C - R0001 - Home Base - (63.54 SQM) - Teaching Space: 1	Student Space (29)	
B00C - R0002 - Principal - (9.07 SQM)	Office (2)	
B00C - R0003 - Practical Activities - 1hb - (16.17 SQM)	Student Space (7)	
B00C - R0010 - Movement - (7.08 SQM)	Not Applicable	Circulation or storage space.
B00F - R0001 - Home Base - (58.66 SQM) - Teaching Space: 1	Student Space (27)	