
VENTILATION AUDIT REPORT



SCHOOL:	Five Islands School (5723)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Lake Macquarie
LOCAL GOVERNMENT AREA:	Lake Macquarie



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00E - R0001 - Hydrotherapy - Spa - (22.68 SQM)	Not Applicable	Circulation or storage space.
B00G - R0002 - Special Programs Room - Type 1 - (64.66 SQM)	Student Space (29)	
B00I - R0001 - Home Base - (68.58 SQM) - Teaching Space: 1	Student Space (31)	
B00I - R0002 - Practical Activities - 1hb - (9.77 SQM)	Student Space (4)	
B00I - R0006 - Practical Activities - 1hb - (9.77 SQM)	Student Space (4)	
B00I - R0007 - Home Base - (68.58 SQM) - Teaching Space: 1	Student Space (31)	
B00J - R0001 - Home Base - (68.58 SQM) - Teaching Space: 1	Student Space (31)	
B00J - R0002 - Practical Activities - 1hb - (9.77 SQM)	Student Space (4)	
B00J - R0006 - Practical Activities - 1hb - (9.77 SQM)	Student Space (4)	
B00J - R0007 - Home Base - (68.58 SQM) - Teaching Space: 1	Student Space (31)	
B00K - R0001 - Home Base - (68.58 SQM) - Teaching Space: 1	Student Space (31)	
B00K - R0002 - Practical Activities - 1hb - (9.77 SQM)	Student Space (4)	
B00K - R0006 - Practical Activities - 1hb - (9.77 SQM)	Student Space (4)	
B00K - R0007 - Home Base - (68.58 SQM) - Teaching Space: 1	Student Space (31)	
OS 505 15099 - OS 505 15099 - Admin Staff/Principal/Secure Store - (76 SQM)	Office (19)	
OS 621 12966 - OS 621 12966 - Learning Unit Single - PWD - (95 SQM)	Student Space (44)	