
VENTILATION AUDIT REPORT



SCHOOL:	Ganmain Public School (1954)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Coolamon

1954 - Ganmain Public School Site Plan (13398)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Reading Area - (47.79 SQM)	Student Space (22)	
B00A - R0002 - Home Base - (98.01 SQM) - Teaching Space: 1	Student Space (45)	
B00A - R0003 - Home Base - M - (47.38 SQM) - Teaching Space: 1	Student Space (21)	
B00A - R0007 - Movement - (7.74 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Staff Room - (17.17 SQM)	Office (4)	
B00A - R0009 - Clerical Office - (10.86 SQM)	Office (2)	
B00A - R0012 - Principal - (11.83 SQM)	Office (2)	
B00A - R0013 - Clerical Office/Workroom - (18.48 SQM)	Office (4)	
B00B - R0002 - Movement - (24.64 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Movement - (36.07 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Special Programs Room - (30.45 SQM)	Student Space (14)	
B00F - R0001 - Withdrawal Space - 1hb - (12.94 SQM)	Student Space (6)	
B00F - R0002 - Home Base - (60.97 SQM) - Teaching Space: 1	Student Space (28)	
B00F - R0003 - Movement - (6.71 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Clerical Office - (59.86 SQM)	Office (14)	