


VENTILATION AUDIT REPORT

SCHOOL:	Gerogery Public School (1969)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Albury
LOCAL GOVERNMENT AREA:	Greater Hume

1969 - Gerogery Public School
Site Plan (12724)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (36.39 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Practical Activities - 1hb - (12.68 SQM)	● Student Space (5)	
B00A - R0003 - Home Base - (54.1 SQM) - Teaching Space: 1	● Student Space (25)	
B00A - R0004 - Withdrawal Space - 1hb - (19.34 SQM)	● Student Space (8)	
B00B - R0001 - Movement - (13.18 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Reading Area - (20.29 SQM)	● Student Space (9)	
B00E - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	● Student Space (27)	
OS 500 18114 - OS 500 18114 - Admin - Library - (133 SQM)	● Office (33)	