


# VENTILATION AUDIT REPORT












<b>SCHOOL:</b>	<b>Gibberagong Environmental Education Centre (5714)</b>
<b>AMU REGION:</b>	<b>Northern Sydney</b>
<b>STATE ELECTORATE:</b>	<b>Hornsby</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Hornsby</b>

5714 - Gibberagong Environmental Education Centre  
Site Plan (12688)



## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0014 - Clerical Office/Workroom - (24.65 SQM)	 Office (6)	
B00A - R0015 - Movement - (54.03 SQM)	Not Applicable	Circulation or storage space.
B00A - R0016 - Special Programs Room - (42.16 SQM)	 Student Space (19)	
B00A - R1002 - Reading Area - (44.91 SQM)	 Student Space (20)	
B00A - R1003 - Clerical Office - (9.49 SQM)	 Office (2)	
B00A - R1004 - Clerical Office - (9.49 SQM)	 Office (2)	
B00A - R1006 - Movement - (20.39 SQM)	Not Applicable	Circulation or storage space.
B00A - R1007 - Dormitory - (17.13 SQM)	 Office (4)	
B00A - R1008 - Dormitory - (17.13 SQM)	 Office (4)	
B00A - R1009 - Dormitory - (17.09 SQM)	 Office (4)	
B00A - R1010 - Dormitory - (17.13 SQM)	 Office (4)	
B00A - R1013 - Staff Kitchen - (17.52 SQM)	 Office (4)	
B00A - R1022 - Staff Room Annexe - (8.37 SQM)	 Office (2)	
B00A - R1023 - Movement - (13.33 SQM)	Not Applicable	Circulation or storage space.