


VENTILATION AUDIT REPORT

SCHOOL:	Girilambone Public School (1986)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Bogan

1986 - Girilambone Public School
Site Plan (10094)










1:1,047

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (47.47 SQM) - Teaching Space: 1	 Student Space (22)	
B00A - R0005 - Reading Area - (23.86 SQM)	 Student Space (11)	
B00A - R0008 - Entry Vestibule - (15.47 SQM)	Not Applicable	Circulation or storage space.
B00A - R0009 - Movement - (7.45 SQM)	Not Applicable	Circulation or storage space.
B00A - R0010 - Staff Kitchen - (12.16 SQM)	 Office (3)	
B00B - R0001 - Communal Space - (19.81 SQM)	 Student Space (9)	
B00C - R0001 - Home Base - (32 SQM) - Teaching Space: 1	 Student Space (14)	
B00D - R0005 - Clerical Office/Workroom - (20.01 SQM)	 Office (5)	
B00D - R0006 - Principal - (18.84 SQM)	 Office (4)	