

VENTILATION AUDIT REPORT

SCHOOL:	Gladstone Public School (1991)
AMU REGION:	North Coast
STATE ELECTORATE:	Oxley
LOCAL GOVERNMENT AREA:	Kempsey

1991 - Gladstone Public School
Site Plan (11866)



1:587

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (18.71 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Clerical Office - (14.24 SQM)	Office (3)	
B00A - R0003 - Principal - (14.24 SQM)	Office (3)	
B00A - R0004 - Entry Vestibule - (23.77 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Staff Room - (21.47 SQM)	Office (5)	
B00A - R0006 - Staff Kitchen - (5.16 SQM)	Office (1)	
B00A - R0007 - Duplicating Workroom - (5.93 SQM)	Office (1)	
B00A - R0008 - Movement - (5.57 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Practical Activities - 1hb - (37.43 SQM)	Student Space (17)	
B00B - R0002 - Home Base - (55.89 SQM) - Teaching Space: 1	Student Space (25)	
B00B - R0003 - Home Base - (53.63 SQM) - Teaching Space: 1	Student Space (24)	
B00C - R0004 - Movement - (9 SQM)	Not Applicable	Circulation or storage space.
B00C - R0008 - Movement - (19.31 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Movement - (14.89 SQM)	Not Applicable	Circulation or storage space.
B00D - R0002 - Canteen - (17.14 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Reading Area - (59.96 SQM)	Student Space (27)	