


VENTILATION AUDIT REPORT

SCHOOL:	Glen William Public School (2020)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Dungog








2020 - Glen William Public School
Site Plan (11769)



Printed: 19-Oct-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (16.95 SQM)	 Office (4)	
B00A - R0009 - Practical Activities - 1hb - (12.01 SQM)	 Student Space (5)	
B00A - R0010 - Practical Activities - 1hb - (16.17 SQM)	 Student Space (7)	
B00A - R0012 - Movement - (27.21 SQM)	Not Applicable	Circulation or storage space.
B00A - R0013 - Home Base - (43.95 SQM) - Teaching Space: 1	 Student Space (20)	
B00D - R0002 - Reading Area - (64.42 SQM)	 Student Space (29)	
OS 500 18120 - OS 500 18120 - Admin - Library - (133 SQM)	 Office (33)	
OS 601 14877 - OS 601 14877 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	