


VENTILATION AUDIT REPORT

SCHOOL:	Goolgowi Public School (2035)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Carrathool

2035 - Goolgowi Public School
Site Plan (10084)













1:1,098

Printed: 20-May-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (16.42 SQM)	 Office (4)	
B00A - R0002 - Principal - (13.02 SQM)	 Office (3)	
B00B - R0004 - Movement - (11.23 SQM)	Not Applicable	Circulation or storage space.
B00B - R0005 - Principal - (13.07 SQM)	 Office (3)	
B00B - R0006 - Clerical Office - (26.79 SQM)	 Office (6)	
B00C - R0005 - Home Base - (86.32 SQM) - Teaching Space: 1	 Student Space (40)	
B00C - R0006 - Home Base - (56.8 SQM) - Teaching Space: 1	 Student Space (26)	
B00C - R0009 - Staff Room - (28.6 SQM)	 Office (7)	
B00D - R0001 - Reading Area - (61.84 SQM)	 Student Space (28)	
B00D - R0003 - Seminar/Study - (9.82 SQM)	 Office (2)	
B00I - R0005 - Reading Area - (91.86 SQM)	 Student Space (42)	