


VENTILATION AUDIT REPORT






| | |
|-------------------------------|------------------------------------|
| SCHOOL: | Goolma Public School (2036) |
| AMU REGION: | North Western NSW |
| STATE ELECTORATE: | Dubbo |
| LOCAL GOVERNMENT AREA: | Mid-Western |

2036 - Goolma Public School
Site Plan (12739)



Ventilation Audit Key

| Category | Description |
|---|--|
|  | Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings. |
|  | Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces. |

| Entity Location | Audit Condition Classification (Capacity) | Comment |
|--|--|---------|
| B00A - R0001 - Practical Activities - 1hb - (15.67 SQM) |  Student Space (7) | |
| B00A - R0002 - Reading Area - (39.48 SQM) |  Student Space (18) | |
| B00B - R0004 - Clerical Office - (15.75 SQM) |  Office (3) | |
| B00B - R0005 - Staff Room - (15.68 SQM) |  Office (3) | |
| B00D - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1 |  Student Space (27) | |