
VENTILATION AUDIT REPORT



SCHOOL:	Gralee School (5730)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Leeton

5730 - Gralee School Site Plan (12956)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations. It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0006 - Movement - (40.23 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Withdrawal - M - (8.46 SQM)	Student Space (3)	
B00A - R0012 - Home Base - M - (58.68 SQM) - Teaching Space: 1	Student Space (27)	
B00A - R0020 - Withdrawal - M - (10.22 SQM)	Student Space (4)	
B00A - R0021 - Withdrawal Space - 1hb - (35.64 SQM)	Student Space (16)	
B00A - R0022 - Withdrawal - M - (36.24 SQM)	Student Space (16)	
B00A - R0024 - Home Base - M - (36 SQM) - Teaching Space: 1	Student Space (16)	
B00A - R0030 - Movement - (38.52 SQM)	Not Applicable	Circulation or storage space.
OS 505 16175 - OS 505 16175 - Admin Staff/Principal/Secure Store - (76 SQM)	Office (19)	
OS 601 12414 - OS 601 12414 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	