
VENTILATION AUDIT REPORT



SCHOOL:	Green Hill Public School (2071)
AMU REGION:	North Coast
STATE ELECTORATE:	Oxley
LOCAL GOVERNMENT AREA:	Kempsey

2071 - Green Hill Public School Site Plan (14706)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0005 - Home Base - (44.16 SQM) - Teaching Space: 1	Student Space (20)	
B00A - R0008 - Staff Room - (18.27 SQM)	Office (4)	
B00A - R0009 - Staff Room Annexe - (5.2 SQM)	Office (1)	
B00A - R0015 - Movement - (5.97 SQM)	Not Applicable	Circulation or storage space.
B00A - R0017 - Special Programs Room - (38 SQM)	Student Space (17)	
B00D - R0002 - Clerical Office - (19.07 SQM)	Office (4)	
B00D - R0004 - Sick Bay - (7.58 SQM)	Student Space (3)	
B00D - R0007 - Movement - (19.47 SQM)	Not Applicable	Circulation or storage space.
B00D - R0008 - Staff Room - (21.38 SQM)	Office (5)	
B00D - R0009 - Staff Kitchen - (5.19 SQM)	Office (1)	
B00D - R0011 - Principal - (17.13 SQM)	Office (4)	
B00D - R0012 - Reading Area - (71.09 SQM)	Student Space (32)	
OS 602 17693 - OS 602 17693 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	