
VENTILATION AUDIT REPORT



SCHOOL:	Gwabegar Public School (2115)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Narrabri

2115 - Gwabegar Public School Site Plan (10096)



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (11.11 SQM)	Office (2)	
B00A - R0002 - Clerical Office/Workroom - (29.7 SQM)	Office (7)	
B00A - R0004 - Movement - (40.28 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Home Base - (37.38 SQM) - Teaching Space: 1	Student Space (17)	
B00A - R0006 - Practical Activities - 1hb - (8.79 SQM)	Student Space (4)	
B00A - R0007 - Withdrawal Space - 1hb - (38.19 SQM)	Student Space (17)	
B00A - R0008 - Staff Room - (15.49 SQM)	Office (3)	
B00B - R0002 - Movement - (12.49 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Reading Area - (37.84 SQM)	Student Space (17)	
B00E - R0001 - Movement - (39.3 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Home Base - (88.38 SQM) - Teaching Space: 1	Student Space (41)	
B00E - R0005 - Practical Activities - 1hb - (6.66 SQM)	Student Space (3)	
B00E - R0006 - Communal Space - (70.75 SQM)	Student Space (32)	