


VENTILATION AUDIT REPORT

SCHOOL:	Hampton Public School (2129)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Lithgow

2129 - Hampton Public School
Site Plan (13072)



1:584

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Principal - (13.82 SQM)	 Office (3)	
B00A - R0003 - Staff Room - (24.31 SQM)	 Office (6)	
B00A - R0006 - Entry Vestibule - (8.11 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Movement - (9.63 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Clerical Office - (10.54 SQM)	 Office (2)	
B00C - R0002 - Reading Area - (42.11 SQM)	 Student Space (19)	
B00E - R0001 - Home Base - (59.89 SQM) - Teaching Space: 1	 Student Space (27)	