

VENTILATION AUDIT REPORT












SCHOOL:	Hannam Vale Public School (2131)
AMU REGION:	North Coast
STATE ELECTORATE:	Port Macquarie
LOCAL GOVERNMENT AREA:	Mid-Coast

2131 - Hannam Vale Public School
Site Plan (10404)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Principal - (15 SQM)	 Office (3)	
B00A - R0002 - Entry Vestibule - (9.61 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Clerical Office - (11.78 SQM)	 Office (2)	
B00A - R0004 - Staff Room - (13.78 SQM)	 Office (3)	
B00B - R0001 - Home Base - (54.46 SQM) - Teaching Space: 1	 Student Space (25)	
B00B - R0003 - Clerical Office - (10.66 SQM)	 Office (2)	
B00C - R0002 - Reading Area - (28.06 SQM)	 Student Space (13)	
B00F - R0004 - Withdrawal Space - 1hb - (14.7 SQM)	 Student Space (6)	
B00F - R0005 - Withdrawal Space - 1hb - (19.87 SQM)	 Student Space (9)	
B00F - R0006 - Seminar/Study - (15.65 SQM)	 Office (3)	
B00F - R0010 - Staff Kitchen - (12.84 SQM)	 Office (3)	
B00H - R0001 - Communal Space - (31.24 SQM)	 Student Space (14)	
B00H - R0002 - Raised Platform - (9.71 SQM)	Not Applicable	Circulation or storage space.