

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Hermidale Public School (2155)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Barwon</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Bogan</b>

2155 - Hermidale Public School  
Site Plan (13080)









1:500

Printed: 20-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Home Base - (50.01 SQM) - Teaching Space: 1	 Student Space (23)	
B00A - R0004 - Staff Room - (14.72 SQM)	 Office (3)	
B00A - R0005 - Movement - (24.65 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Clerical Office - (32.12 SQM)	 Office (8)	
B00C - R0001 - Clerical Office - (11.23 SQM)	 Office (2)	
B00C - R0002 - Home Base - (41.44 SQM) - Teaching Space: 1	 Student Space (19)	
B00C - R0004 - Special Programs Room - (20.3 SQM)	 Student Space (9)	