

VENTILATION AUDIT REPORT

SCHOOL:	Hernani Public School (2156)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Clarence Valley

2156 - Hernani Public School
Site Plan (12644)








1:701

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0005 - Clerical Office/Workroom - (13.93 SQM)	 Office (3)	
B00A - R0007 - Home Base - (53.39 SQM) - Teaching Space: 1	 Student Space (24)	
B00C - R0001 - Reading Area - (16.46 SQM)	 Student Space (7)	
B00C - R0002 - Movement - (7.1 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Special Programs Room - (54.83 SQM)	 Student Space (25)	
B00D - R0002 - Movement - (12.78 SQM)	Not Applicable	Circulation or storage space.
B00D - R0003 - Canteen - (6.91 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Communal Space - (59.98 SQM)	 Student Space (27)	