


VENTILATION AUDIT REPORT

SCHOOL:	Hill End Public School (2161)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Bathurst

2161 - Hill End Public School
Site Plan (13351)



1:372

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Staff Room - (35.89 SQM)	Office (8)	
B00A - R0003 - Movement - (21.46 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Home Base - (42.49 SQM) - Teaching Space: 1	Student Space (19)	
B00A - R0006 - Withdrawal Space - 1hb - (32.59 SQM)	Student Space (15)	
B00A - R0007 - Movement - (13.99 SQM)	Not Applicable	Circulation or storage space.
B00A - R0010 - Reading Area - (35.13 SQM)	Student Space (16)	
B00A - R0011 - Movement - (17.97 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (13.52 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Reading Area - (59.91 SQM)	Student Space (27)	